## 3. Internal Photograph of EUT

Brand Name: Avvio; Model Name: Avvio 935S; Avvio 935

Report No.: EP322601



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WVBA935X Page Number : 12 of 30 Report Issued Date : Mar. 15, 2013

Brand Name: Avvio; Model Name: Avvio 935S; Avvio 935




TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WVBA935X Page Number : 13 of 30
Report Issued Date : Mar. 15, 2013


Brand Name: Avvio; Model Name: Avvio 935S; Avvio 935



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WVBA935X Page Number : 14 of 30 Report Issued Date : Mar. 15, 2013




TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WVBA935X Page Number : 15 of 30 Report Issued Date : Mar. 15, 2013




SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WVBA935X Page Number : 16 of 30
Report Issued Date : Mar. 15, 2013




TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WVBA935X Page Number : 17 of 30
Report Issued Date : Mar. 15, 2013

Report No.: EP322601



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WVBA935X Page Number : 18 of 30
Report Issued Date : Mar. 15, 2013
Report Version : Rev. 01

Report No.: EP322601



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WVBA935X Page Number : 19 of 30
Report Issued Date : Mar. 15, 2013

Report No.: EP322601



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WVBA935X Page Number : 20 of 30
Report Issued Date : Mar. 15, 2013

Report No.: EP322601




TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WVBA935X Page Number : 21 of 30
Report Issued Date : Mar. 15, 2013

: Rev. 01


Report Version



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WVBA935X Page Number : 22 of 30
Report Issued Date : Mar. 15, 2013
Report Version : Rev. 01




TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WVBA935X Page Number : 23 of 30
Report Issued Date : Mar. 15, 2013
Report Version : Rev. 01




TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WVBA935X Page Number : 24 of 30 Report Issued Date : Mar. 15, 2013

Brand Name: Avvio; Model Name: Avvio 935S; Avvio 935




TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WVBA935X Page Number : 25 of 30
Report Issued Date : Mar. 15, 2013
Report Version : Rev. 01

Report No.: EP322601



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WVBA935X Page Number : 26 of 30
Report Issued Date : Mar. 15, 2013
Report Version : Rev. 01

Report No.: EP322601




TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WVBA935X Page Number : 27 of 30 Report Issued Date : Mar. 15, 2013

Report No.: EP322601



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WVBA935X Page Number : 28 of 30 Report Issued Date : Mar. 15, 2013

Report No.: EP322601



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WVBA935X Page Number : 29 of 30
Report Issued Date : Mar. 15, 2013
Report Version : Rev. 01

Report No.: EP322601



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WVBA935X Page Number : 30 of 30 Report Issued Date : Mar. 15, 2013