## 1. External Photograph of EUT

Brand Name: Avvio / Model Name: HT850HS

Report No.: EP132510-01



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WVBHT850HS Page Number : 1 of 25
Report Issued Date : Jul. 01, 2011
Report Version : Rev. 01



Report No.: EP132510-01



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WVBHT850HS

Page Number : 2 of 25 Report Issued Date : Jul. 01, 2011 Report Version : Rev. 01



Report No.: EP132510-01



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WVBHT850HS

Page Number : 3 of 25 Report Issued Date : Jul. 01, 2011 Report Version : Rev. 01



Report No.: EP132510-01



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WVBHT850HS

Page Number : 4 of 25 Report Issued Date : Jul. 01, 2011 Report Version : Rev. 01



Report No.: EP132510-01



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WVBHT850HS

Page Number : 5 of 25 Report Issued Date : Jul. 01, 2011 Report Version : Rev. 01



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WVBHT850HS Page Number : 6 of 25
Report Issued Date : Jul. 01, 2011
Report Version : Rev. 01

## 2. Photograph of Accessory

Brand Name: Avvio / Model Name: HT850HS

Report No.: EP132510-01

## **List of Accessory:**

Specification of Accessory		
IAC Adapter	Brand Name	Aohai
	Model Name	A361-0500650U
Battery	Brand Name	Avvio
	Model Name	LB1500-03
USB Cable	Туре	0.85m shielded without core

**Remark:** For accessories equipped with this EUT, please refer to the following photos.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WVBHT850HS Page Number : 7 of 25
Report Issued Date : Jul. 01, 2011
Report Version : Rev. 01



Report No.: EP132510-01




TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WVBHT850HS

Page Number : 8 of 25 Report Issued Date : Jul. 01, 2011 Report Version : Rev. 01



Report No.: EP132510-01




TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WVBHT850HS

: 9 of 25 Page Number Report Issued Date : Jul. 01, 2011 Report Version : Rev. 01



Report No.: EP132510-01



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WVBHT850HS

: 10 of 25 Page Number Report Issued Date : Jul. 01, 2011 Report Version : Rev. 01



Report No.: EP132510-01



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WVBHT850HS


: 11 of 25 Page Number Report Issued Date : Jul. 01, 2011 Report Version : Rev. 01





TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WVBHT850HS Page Number : 12 of 25
Report Issued Date : Jul. 01, 2011
Report Version : Rev. 01

Report No.: EP132510-01




TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WVBHT850HS

: 13 of 25 Page Number Report Issued Date : Jul. 01, 2011 Report Version : Rev. 01



Report No.: EP132510-01



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WVBHT850HS

Page Number : 14 of 25 Report Issued Date : Jul. 01, 2011 Report Version : Rev. 01





TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WVBHT850HS Page Number : 15 of 25
Report Issued Date : Jul. 01, 2011
Report Version : Rev. 01





TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WVBHT850HS Page Number : 16 of 25
Report Issued Date : Jul. 01, 2011
Report Version : Rev. 01



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WVBHT850HS Page Number : 17 of 25
Report Issued Date : Jul. 01, 2011
Report Version : Rev. 01