


Appendix B. Setup Photographs


<Radiated Emission>

H-Plane

LF



HF



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WVBA418S Page Number : B1 of B2
Report Issued Date : Nov. 29, 2012
Report Version : Rev. 01


Report No.: FG2N1501





E2-Plane

LF



HF



SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WVBA418S Page Number : B2 of B2
Report Issued Date : Nov. 29, 2012
Report Version : Rev. 01

Report No.: FG2N1501