

Report No.: FA192301

Appendix D. Product Photos





TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WVBAVVIO515 Page Number : D1 of D1
Report Issued Date : Oct. 28, 2011
Report Version : Rev. 01



Report No.: FA192301

Appendix E. Test Setup Photos





Right Cheek









Left Tilted



Face of the DUT with Phantom 1.5 cm Gap



Bottom of the DUT with Phantom 1.5 cm Gap

SPORTON INTERNATIONAL (KUNSHAN) INC

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WVBAVVIO515 Page Number : E1 of E1
Report Issued Date : Oct. 28, 2011
Report Version : Rev. 01