

Report No. : FA431410

Appendix D. Test Setup Photos





Right Cheek








SPORTON INTERNATIONAL (SHENZHEN) INC.

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: WVBA814X Page Number : D1 of D2
Report Issued Date : Mar. 20, 2014
Report Version : Rev. 01







Front of the DUT with Phantom 1.5 cm Gap

Back of the DUT with Phantom 1.5 cm Gap

Report No.: FA431410

SPORTON INTERNATIONAL (SHENZHEN) INC.

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: WVBA814X Page Number : D2 of D2 Report Issued Date : Mar. 20, 2014

Report Version : Rev. 01