

Appendix B. Setup Photographs

<Conducted Emission>

Mode 1



Mode 4



SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WVBA9781

: B1 of B2 Page Number Report Issued Date: Mar. 22, 2013

Report No.: FC313006


Report Version : Rev. 01




<Radiated Emission>

Mode 4

LF







SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WVBA9781

: B2 of B2 Page Number Report Issued Date: Mar. 22, 2013

Report No.: FC313006

Report Version : Rev. 01