



## Appendix B. Setup Photographs

## <Conducted Emission>

## Mode 1





SPORTON International (ShenZhen) INC.

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: WVBAQ145X Page Number : B1 of B2
Report Issued Date : Mar. 24, 2017
Report Version : Rev. 01

Report Template No.: BU5-FR15CBT Version 1.1

Report No.: FR722807A







## <Radiated Emission>

X Plane

LF



HF



SPORTON International (ShenZhen) INC.

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: WVBAQ145X Page Number : B1 of B2
Report Issued Date : Mar. 24, 2017
Report Version : Rev. 01
Report Template No.: BU5-FR15CBT Version 1.1

Report No.: FR722807A