## 3. Internal Photograph of EUT

Brand Name: Avvio; Model Name: Avvio 814

Report No.: EP431410



TEL: 86-755- 3320-2398 FCC ID: WVBA814X

Page Number : 12 of 29
Report Issued Date : Mar. 20, 2014

Report No.: EP431410

Brand Name: Avvio; Model Name: Avvio 814



TEL: 86-755- 3320-2398 FCC ID: WVBA814X

Page Number : 13 of 29
Report Issued Date : Mar. 20, 2014

**Report No.: EP431410** 



TEL: 86-755- 3320-2398 FCC ID: WVBA814X


Page Number : 14 of 29
Report Issued Date : Mar. 20, 2014

**Report No.: EP431410** 




TEL: 86-755- 3320-2398 FCC ID: WVBA814X Page Number : 15 of 29
Report Issued Date : Mar. 20, 2014






SPORTON INTERNATIONAL (SHENZHEN) INC.

TEL : 86-755- 3320-2398 FCC ID : WVBA814X Page Number : 16 of 29
Report Issued Date : Mar. 20, 2014



**Report No.: EP431410** 




TEL: 86-755-3320-2398 FCC ID: WVBA814X

: 17 of 29 Page Number Report Issued Date: Mar. 20, 2014

: Rev. 01

Report Version



Brand Name: Avvio; Model Name: Avvio 814 09 30 9 20 09 30 07 09 02 0,8 06 **00 l** 01


SPORTON INTERNATIONAL (SHENZHEN) INC.

TEL: 86-755-3320-2398 FCC ID: WVBA814X

Page Number : 18 of 29 Report Issued Date: Mar. 20, 2014


**Report No.: EP431410** 

**Report No.: EP431410** 



TEL: 86-755- 3320-2398 FCC ID: WVBA814X Page Number : 19 of 29
Report Issued Date : Mar. 20, 2014

Report No.: EP431410




TEL: 86-755- 3320-2398 FCC ID: WVBA814X Page Number : 20 of 29
Report Issued Date : Mar. 20, 2014

Report No.: EP431410



TEL: 86-755- 3320-2398 FCC ID: WVBA814X Page Number : 21 of 29
Report Issued Date : Mar. 20, 2014


**Report No.: EP431410** 



TEL: 86-755- 3320-2398 FCC ID: WVBA814X Page Number : 22 of 29
Report Issued Date : Mar. 20, 2014




**Report No.: EP431410** 



TEL: 86-755-3320-2398 FCC ID: WVBA814X


: 23 of 29 Page Number Report Issued Date: Mar. 20, 2014

Report No.: EP431410




TEL: 86-755- 3320-2398 FCC ID: WVBA814X Page Number : 24 of 29
Report Issued Date : Mar. 20, 2014

Report No.: EP431410




TEL: 86-755- 3320-2398 FCC ID: WVBA814X Page Number : 25 of 29
Report Issued Date : Mar. 20, 2014

Report No.: EP431410



TEL: 86-755- 3320-2398 FCC ID: WVBA814X Page Number : 26 of 29
Report Issued Date : Mar. 20, 2014


Report No.: EP431410



TEL: 86-755- 3320-2398 FCC ID: WVBA814X Page Number : 27 of 29
Report Issued Date : Mar. 20, 2014




**Report No.: EP431410** 



TEL: 86-755-3320-2398 FCC ID: WVBA814X

Page Number : 28 of 29 Report Issued Date: Mar. 20, 2014





TEL: 86-755- 3320-2398 FCC ID: WVBA814X Page Number : 29 of 29
Report Issued Date : Mar. 20, 2014