3. Internal Photograph of EUT

Brand Name: Avvio / Model Name: Avvio L800S, Avvio L800

Report No.: EP580514



TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: WVBAL800X Page Number : 12 of 40
Report Issued Date : Sep. 15, 2015
Report Version : Rev. 01



Report No.: EP580514



TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: WVBAL800X

: 13 of 40 Page Number Report Issued Date : Sep. 15, 2015 Report Version : Rev. 01



Report No.: EP580514



TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: WVBAL800X

: 14 of 40 Page Number Report Issued Date : Sep. 15, 2015 Report Version : Rev. 01




Report No.: EP580514



TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: WVBAL800X

Page Number : 15 of 40 Report Issued Date : Sep. 15, 2015 : Rev. 01 Report Version

Report No.: EP580514



Brand Name: Avvio / Model Name: Avvio L800S, Avvio L800

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: WVBAL800X Page Number : 16 of 40
Report Issued Date : Sep. 15, 2015
Report Version : Rev. 01



30

Report No.: EP580514

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: WVBAL800X

: 17 of 40 Page Number Report Issued Date : Sep. 15, 2015 Report Version : Rev. 01



Brand Name: Avvio / Model Name: Avvio L800S, Avvio L800 50 07 30 07 06 00 30 04 08 ար ժամաժավարկական անավայան հանավային հանականական հանականում է անականական հանականական հանական հանակային հա

SPORTON INTERNATIONAL (SHENZHEN) INC.

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: WVBAL800X

Page Number : 18 of 40 Report Issued Date : Sep. 15, 2015 : Rev. 01 Report Version

Report No.: EP580514



09 40 30 20 09 80 20 30 09 40 mitaninahalimikalimikadinahalimikalimihalimikalimihalimihalimihalimi 30

09

06 00 L 01

04

ավավակակականության անականականությունը և արարականությունը և արարականության և արարականության և արարականության ան

0,8


Brand Name: Avvio / Model Name: Avvio L800S, Avvio L800

Report No.: EP580514

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: WVBAL800X


Page Number : 19 of 40 Report Issued Date : Sep. 15, 2015 : Rev. 01 Report Version

Report No.: EP580514



TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: WVBAL800X Page Number : 20 of 40
Report Issued Date : Sep. 15, 2015
Report Version : Rev. 01


Report No.: EP580514




SPORTON INTERNATIONAL (SHENZHEN) INC.


TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: WVBAL800X Page Number : 21 of 40
Report Issued Date : Sep. 15, 2015
Report Version : Rev. 01

Report No.: EP580514



TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: WVBAL800X Page Number : 22 of 40
Report Issued Date : Sep. 15, 2015
Report Version : Rev. 01






SPORTON INTERNATIONAL (SHENZHEN) INC.

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: WVBAL800X Page Number : 23 of 40
Report Issued Date : Sep. 15, 2015
Report Version : Rev. 01

Report No.: EP580514



SPORTON INTERNATIONAL (SHENZHEN) INC.

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: WVBAL800X Page Number : 24 of 40
Report Issued Date : Sep. 15, 2015
Report Version : Rev. 01