

Report No.: FA951106

Appendix D - Product Photos




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: WVBW172A Report Issued Date : May 26, 2009
Report Version : Rev. 01




Report No. : FA951106

Appendix E - Test Setup Photos




Right Cheek




Right Tilted


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: WVBW172A Report Issued Date: May 26, 2009

Report Version : Rev. 01





Left Cheek




Left Tilted


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: WVBW172A Report Issued Date: May 26, 2009

Report Version : Rev. 01





DUT Face with Phantom 15 mm Gap



DUT Bottom with Phantom 15 mm Gap

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: WVBW172A Report Issued Date : May 26, 2009
Report Version : Rev. 01