## 1. External Photographs of EUT

Model Name: B525V1

Report No.: EP951106



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: WVBW172A Page Number : 1 of 22 Issued Date : May 26, 2009 Report Version : Rev. 01





Page Number : 2 of 22
Issued Date : May 26, 2009
Report Version : Rev. 01

Report No.: EP951106




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: WVBW172A Page Number : 3 of 22
Issued Date : May 26, 2009
Report Version : Rev. 01





Page Number : 4 of 22 Issued Date : May 26, 2009 Report Version : Rev. 01





Page Number : 5 of 22 Issued Date : May 26, 2009 Report Version : Rev. 01





Page Number : 6 of 22 Issued Date : May 26, 2009 Report Version : Rev. 01

Report No.: EP951106

## 2. Photographs of Accessories

Model Name: B525V1

Report No.: EP951106



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: WVBW172A Page Number : 7 of 22 Issued Date : May 26, 2009 Report Version : Rev. 01





Page Number : 8 of 22 Issued Date : May 26, 2009 Report Version : Rev. 01



Model Name: B525V1

Report No.: EP951106



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: WVBW172A


Page Number : 9 of 22 Issued Date : May 26, 2009 Report Version : Rev. 01


Model Name: B525V1

Report No.: EP951106




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: WVBW172A Page Number : 10 of 22
Issued Date : May 26, 2009
Report Version : Rev. 01





Page Number : 11 of 22 Issued Date : May 26, 2009 Report Version : Rev. 01

Report No.: EP951106



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: WVBW172A Page Number : 12 of 22 Issued Date : May 26, 2009 Report Version : Rev. 01





Page Number : 13 of 22 Issued Date : May 26, 2009 Report Version : Rev. 01

Report No.: EP951106