

Appendix D. Product Photos





TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WVBG6 Page Number : D1 of D1
Report Issued Date : May 11, 2011
Report Version : Rev. 01

Report No.: FA140742



Report No. : FA140742

Appendix E. Test Setup Photos



Right Cheek

Right Tilted





Left Cheek

Left Tilted







Bottom of the DUT with Phantom 1.5 cm Gap

SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WVBG6 Page Number : E1 of E1
Report Issued Date : May 11, 2011
Report Version : Rev. 01