## 1. External Photograph of EUT

Brand Name: Avvio; Model Name: Avvio 938

Report No.: EP410704



TEL: 86-755-3320-2398 FCC ID: WVBA938X Page Number : 1 of 24



Report No.: EP410704



TEL: 86-755-3320-2398 FCC ID: WVBA938X

Page Number : 2 of 24

Report No.: EP410704



TEL : 86-755- 3320-2398 FCC ID : WVBA938X Page Number : 3 of 24

Report No.: EP410704



TEL : 86-755- 3320-2398 FCC ID : WVBA938X Page Number : 4 of 24

Report No.: EP410704



TEL : 86-755- 3320-2398 FCC ID : WVBA938X Page Number : 5 of 24

Report No.: EP410704



TEL : 86-755- 3320-2398 FCC ID : WVBA938X Page Number : 6 of 24

## 2. Photograph of Accessory

Brand Name: Avvio; Model Name: Avvio 938

Report No.: EP410704

**List of Accessory:** 

Specification of Accessory		
IAC: Adapter	Brand Name	Avvio
	Model Name	AD-H50U50
Battery	Brand Name	Avvio
	Model Name	BL-5F
USB Cable	Signal Line Type	1.0m, shielded cable, without core
Earphone	Signal Line Type	1.0m, non-shielded cable

**Remark:** For accessories equipped with this EUT, please refer to the following photos.

SPORTON INTERNATIONAL (SHENZHEN) INC. Page Number : 7 of 24
TEL: 86-755- 3320-2398 Report Issued Date : Feb. 18, 2014

FCC ID: WVBA938X Report Version : Rev. 01

Report No.: EP410704



TEL : 86-755- 3320-2398 FCC ID : WVBA938X Page Number : 8 of 24


Report No.: EP410704



TEL: 86-755- 3320-2398 FCC ID: WVBA938X Page Number : 9 of 24



Report No.: EP410704




TEL: 86-755-3320-2398 FCC ID: WVBA938X

Page Number : 10 of 24 Report Issued Date: Feb. 18, 2014

Report Version : Rev. 01



Report No.: EP410704



TEL: 86-755-3320-2398 FCC ID: WVBA938X

Page Number : 11 of 24 Report Issued Date: Feb. 18, 2014

Report Version : Rev. 01