

Appendix D. Product Photos





Report No.: FA192301-01








SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WVBA515S Page Number : D1 of D1
Report Issued Date : Mar. 22, 2012
Report Version : Rev. 01



Report No.: FA192301-01

Appendix E. **Test Setup Photos**





Right Cheek








Left Cheek

Left Tilted





Face of the DUT with Phantom 1.5 cm Gap



Bottom of the DUT with Phantom 1.5 cm Gap

SPORTON INTERNATIONAL (KUNSHAN) INC

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WVBA515S

Page Number : E1 of E1 Report Issued Date: Mar. 22, 2012 Report Version : Rev. 01