3. Internal Photograph of EUT

Brand Name: Avvio; Model Name: Avvio 917S/Avvio 917

Report No.: EP2D1103



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WVBA917 Page Number : 12 of 32
Report Issued Date : Dec. 04, 2012
Report Version : Rev. 01

Report No.: EP2D1103



SPORTON INTERNATIONAL (KUNSHAN) INC.


TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WVBA917 Page Number : 13 of 32
Report Issued Date : Dec. 04, 2012
Report Version : Rev. 01



SPORTON INTERNATIONAL (KUNSHAN) INC.


TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WVBA917 Page Number : 14 of 32
Report Issued Date : Dec. 04, 2012
Report Version : Rev. 01

Report No.: EP2D1103



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WVBA917 Page Number : 15 of 32
Report Issued Date : Dec. 04, 2012
Report Version : Rev. 01


Brand Name: Avvio; Model Name: Avvio 917S/Avvio 917



SPORTON INTERNATIONAL (KUNSHAN) INC.


TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WVBA917 Page Number : 16 of 32
Report Issued Date : Dec. 04, 2012
Report Version : Rev. 01

Report No.: EP2D1103



SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WVBA917 Page Number : 17 of 32
Report Issued Date : Dec. 04, 2012
Report Version : Rev. 01




SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WVBA917

Page Number : 18 of 32 Report Issued Date : Dec. 04, 2012 Report Version : Rev. 01


Report No.: EP2D1103



SPORTON INTERNATIONAL (KUNSHAN) INC.


TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WVBA917 Page Number : 19 of 32
Report Issued Date : Dec. 04, 2012
Report Version : Rev. 01

Report No.: EP2D1103



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WVBA917 Page Number : 20 of 32
Report Issued Date : Dec. 04, 2012
Report Version : Rev. 01

Report No.: EP2D1103



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WVBA917 Page Number : 21 of 32
Report Issued Date : Dec. 04, 2012
Report Version : Rev. 01

Report No.: EP2D1103




SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WVBA917 Page Number : 22 of 32
Report Issued Date : Dec. 04, 2012
Report Version : Rev. 01




TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WVBA917 Page Number : 23 of 32
Report Issued Date : Dec. 04, 2012
Report Version : Rev. 01






TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WVBA917 Page Number : 24 of 32
Report Issued Date : Dec. 04, 2012
Report Version : Rev. 01



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WVBA917 Page Number : 25 of 32
Report Issued Date : Dec. 04, 2012
Report Version : Rev. 01


Report No.: EP2D1103



SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WVBA917 Page Number : 26 of 32
Report Issued Date : Dec. 04, 2012
Report Version : Rev. 01

otographs of EUT Report No.: EP2D1103



Brand Name: Avvio; Model Name: Avvio 917S/Avvio 917

SPORTON INTERNATIONAL (KUNSHAN) INC.


TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WVBA917 Page Number : 27 of 32
Report Issued Date : Dec. 04, 2012
Report Version : Rev. 01

Report No.: EP2D1103




TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WVBA917 Page Number : 28 of 32
Report Issued Date : Dec. 04, 2012
Report Version : Rev. 01

Report No.: EP2D1103



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WVBA917 Page Number : 29 of 32
Report Issued Date : Dec. 04, 2012
Report Version : Rev. 01




TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WVBA917 Page Number : 30 of 32
Report Issued Date : Dec. 04, 2012
Report Version : Rev. 01



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WVBA917 Page Number : 31 of 32
Report Issued Date : Dec. 04, 2012
Report Version : Rev. 01

Report No.: EP2D1103



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WVBA917 Page Number : 32 of 32
Report Issued Date : Dec. 04, 2012
Report Version : Rev. 01