


## Appendix B. Setup Photographs


## <Radiated Emission>

E1-Plane

LF



HF



SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WVBAX89 Page Number : B1 of B2
Report Issued Date : Oct. 11, 2012
Report Version : Rev. 01


Report No. : FG282301






E2-Plane

LF



HF



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WVBAX89 Page Number : B2 of B2
Report Issued Date : Oct. 11, 2012
Report Version : Rev. 01

Report No.: FG282301