

80 20 09 50 80 40 30 09 20

07 90

Brand Name: Avvio / Model Name: Avvio 489, Avvio 489S

Report No.: EP562501

50 10 500 80

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: WVBA489X

Page Number : 32 of 49 Report Issued Date : Jul. 17, 2015 Report Version : Rev. 01



20 30 07 09 0,8 06

Report No.: EP562501

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: WVBA489X

Page Number : 33 of 49 Report Issued Date : Jul. 17, 2015 Report Version : Rev. 01



20 30 07


Report No.: EP562501

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: WVBA489X

Page Number : 34 of 49 Report Issued Date : Jul. 17, 2015 Report Version : Rev. 01




Report No.: EP562501



TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: WVBA489X

Page Number : 35 of 49 Report Issued Date : Jul. 17, 2015 Report Version : Rev. 01



TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: WVBA489X Page Number : 36 of 49
Report Issued Date : Jul. 17, 2015
Report Version : Rev. 01



20

30

07

Brand Name: Avvio / Model Name: Avvio 489, Avvio 489S

Report No.: EP562501

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: WVBA489X

Page Number : 37 of 49 Report Issued Date : Jul. 17, 2015 Report Version : Rev. 01



Brand Name: Avvio / Model Name: Avvio 489, Avvio 489S 20 30

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: WVBA489X

Page Number : 38 of 49 Report Issued Date : Jul. 17, 2015 Report Version : Rev. 01

Report No.: EP562501




80 60 20 30 07 09 09 0,8 06 06 001 01 08

Report No.: EP562501

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: WVBA489X

Page Number : 39 of 49 Report Issued Date : Jul. 17, 2015 Report Version : Rev. 01




TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: WVBA489X

Page Number : 40 of 49 Report Issued Date : Jul. 17, 2015 Report Version : Rev. 01



Brand Name: Avvio / Model Name: Avvio 489, Avvio 489S




TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: WVBA489X


Page Number : 41 of 49 Report Issued Date : Jul. 17, 2015 Report Version : Rev. 01

Report No.: EP562501




TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: WVBA489X Page Number : 42 of 49
Report Issued Date : Jul. 17, 2015
Report Version : Rev. 01






SPORTON INTERNATIONAL (SHENZHEN) INC.

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: WVBA489X Page Number : 43 of 49
Report Issued Date : Jul. 17, 2015
Report Version : Rev. 01




SPORTON INTERNATIONAL (SHENZHEN) INC.

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: WVBA489X Page Number : 44 of 49
Report Issued Date : Jul. 17, 2015
Report Version : Rev. 01



TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: WVBA489X Page Number : 45 of 49
Report Issued Date : Jul. 17, 2015
Report Version : Rev. 01



Brand Name: Avvio / Model Name: Avvio 489, Avvio 489S

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: WVBA489X Page Number : 46 of 49
Report Issued Date : Jul. 17, 2015
Report Version : Rev. 01



x/Rx> 30


Report No.: EP562501

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: WVBA489X

Page Number : 47 of 49 Report Issued Date : Jul. 17, 2015 Report Version : Rev. 01



Report No.: EP562501




TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: WVBA489X

Page Number : 48 of 49 Report Issued Date : Jul. 17, 2015 Report Version : Rev. 01



Report No.: EP562501



TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: WVBA489X

Page Number : 49 of 49 Report Issued Date : Jul. 17, 2015

Report Version : Rev. 01