

Report No.: FR2O2302B

Appendix B. Setup Photographs

<Conducted Emission>



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WVBA790X Page Number : B1 of B2
Report Issued Date : Nov. 13, 2012
Report Version : Rev. 01




<Radiated Emission>

LF



HF



SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WVBA790X Page Number : B2 of B2
Report Issued Date : Nov. 13, 2012
Report Version : Rev. 01

Report No.: FR2O2302B