3. Internal Photograph of EUT

Brand Name: Avvio; Model Name: Avvio 516S, Avvio 516

Report No.: EP312403



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WVBA516 Page Number : 12 of 31
Report Issued Date : Mar. 01, 2013
Report Version : Rev. 01



SPORTON INTERNATIONAL (KUNSHAN) INC.


TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WVBA516 Page Number : 13 of 31
Report Issued Date : Mar. 01, 2013
Report Version : Rev. 01




Brand Name: Avvio; Model Name: Avvio 516S, Avvio 516

SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WVBA516 Page Number : 14 of 31
Report Issued Date : Mar. 01, 2013
Report Version : Rev. 01







TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WVBA516


Page Number : 15 of 31 Report Issued Date : Mar. 01, 2013 Report Version : Rev. 01



Brand Name: Avvio; Model Name: Avvio 516S, Avvio 516

SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WVBA516 Page Number : 16 of 31
Report Issued Date : Mar. 01, 2013
Report Version : Rev. 01






SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WVBA516 Page Number : 17 of 31
Report Issued Date : Mar. 01, 2013
Report Version : Rev. 01





SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WVBA516 Page Number : 18 of 31
Report Issued Date : Mar. 01, 2013
Report Version : Rev. 01






TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WVBA516

Page Number : 19 of 31 Report Issued Date : Mar. 01, 2013 Report Version : Rev. 01





TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WVBA516 Page Number : 20 of 31
Report Issued Date : Mar. 01, 2013
Report Version : Rev. 01



SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WVBA516 Page Number : 21 of 31
Report Issued Date : Mar. 01, 2013
Report Version : Rev. 01



Brand Name: Avvio; Model Name: Avvio 516S, Avvio 516

SPORTON INTERNATIONAL (KUNSHAN) INC.


TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WVBA516 Page Number : 22 of 31
Report Issued Date : Mar. 01, 2013
Report Version : Rev. 01



Brand Name: Avvio; Model Name: Avvio 516S, Avvio 516

SPORTON INTERNATIONAL (KUNSHAN) INC.


TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WVBA516 Page Number : 23 of 31
Report Issued Date : Mar. 01, 2013
Report Version : Rev. 01






SPORTON INTERNATIONAL (KUNSHAN) INC.


TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WVBA516 Page Number : 24 of 31
Report Issued Date : Mar. 01, 2013
Report Version : Rev. 01





SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WVBA516 Page Number : 25 of 31
Report Issued Date : Mar. 01, 2013
Report Version : Rev. 01



Brand Name: Avvio; Model Name: Avvio 516S, Avvio 516

SPORTON INTERNATIONAL (KUNSHAN) INC.


TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WVBA516 Page Number : 26 of 31
Report Issued Date : Mar. 01, 2013
Report Version : Rev. 01

Brand Name: Avvio; Model Name: Avvio 516S, Avvio 516


SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WVBA516 Page Number : 27 of 31
Report Issued Date : Mar. 01, 2013
Report Version : Rev. 01


Report No.: EP312403



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WVBA516 Page Number : 28 of 31
Report Issued Date : Mar. 01, 2013
Report Version : Rev. 01



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WVBA516 Page Number : 29 of 31
Report Issued Date : Mar. 01, 2013
Report Version : Rev. 01






SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WVBA516 Page Number : 30 of 31
Report Issued Date : Mar. 01, 2013
Report Version : Rev. 01





SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WVBA516 Page Number : 31 of 31
Report Issued Date : Mar. 01, 2013
Report Version : Rev. 01