

Report No.: FA251703

Appendix D. Product Photos






SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WVBA831 Page Number : D1 of D2
Report Issued Date : Aug. 06, 2012
Report Version : Rev. 01



Report No. : FA251703

Antenna Location:



Antenna	Length	Width
WWAN Antenna (Tx / Rx)	4.5 cm	1.1 cm
WLAN & Bluetooth Antenna (Tx / Rx)	1.2 cm	1.4 cm

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WVBA831 Page Number : D2 of D2
Report Issued Date : Aug. 06, 2012
Report Version : Rev. 01



Report No.: FA251703

Appendix E. **Test Setup Photos**





Right Cheek









Left Tilted



Back of the DUT with Phantom 1 cm Gap (With Headset)

SPORTON INTERNATIONAL (KUNSHAN) INC

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WVBA831

Page Number : E1 of E2 Report Issued Date: Aug. 06, 2012 Report Version : Rev. 01




Report No.: FA251703

Front of the DUT with Phantom 1 cm Gap

Back of the DUT with Phantom 1 cm Gap







Bottom Side of the DUT with Phantom 1 cm Gap



Left Side of the DUT with Phantom 1 cm Gap



Right Side of the DUT with Phantom 1 cm Gap

SPORTON INTERNATIONAL (KUNSHAN) INC

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WVBA831 Page Number : E2 of E2
Report Issued Date : Aug. 06, 2012

Report Version : Rev. 01