

Report No.: FA132510-01A

## Appendix D. Product Photos



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: WVBHT850HS Page Number : D1 of D2
Report Issued Date : Jul. 01, 2011
Report Version : Rev. 01



Report No.: FA132510-01A

## Appendix E. **Test Setup Photos**





Front Face of the DUT with Phantom 10 mm Gap

Rear Face of the DUT with Phantom 10 mm Gap





Right Side of the DUT with Phantom 10 mm Gap

Left Side of the DUT with Phantom 10 mm Gap





Top Side of the DUT with Phantom 10 mm Gap Bottom Side of the DUT with Phantom 10 mm Gap

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: WVBHT850HS Page Number : E1 of E1 Report Issued Date: Jul. 01, 2011 Report Version : Rev. 01