

- 1.) Kindly provide a corrected application Form 731 with the Applicant's responsible party to receive the Grant, telephone, fax, and email [Lines 4, 5(a), 5(b), and 5(c)]. Please also remember that RF power must be shown on page 2 [Line 6(a)].
- SGS—Already revised. Pls refer to WVLP268A001F001 application form rev1.pdf
- Please provide a Manual with all required compliance language.
  SGS— Already revised. Pls refer to WVLP268A001F001 user manual rev1.pdf
- Please provide an RF Exposure exhibit.
  SGS—Pls refer to WVLP268A001F001 RF Exposure report.pdf
- 4.) AC Conducted test must be performed without the strip outlet. This is generally OK for CE work, but not for ANSI C63.4. Please provide revised AC Conducted Test Setup photos. SGS—Already revised the test setup photos. Pls refer to WVLP268A001F001 test setup photos rev1.pdf