
Test report No.: 31FE0078-SH-01-A-R1

: 13 of 41 Page Issued date : August 1, 2011 : WWGZ2200 FCC ID

APPENDIX 1: Photographs of test setup

Conducted emission







UL Japan, Inc. Shonan EMC Lab.


1-22-3 Megumigaoka, Hiratsuka-shi, Kanagawa-ken, 259-1220 JAPAN

Telephone +81 463 50 6400 : +81 463 50 6401 Facsimile


 $Test\ report\ No.\ :\ 31FE0078\text{-}SH\text{-}01\text{-}A\text{-}R1$

Page : 14 of 41 Issued date : August 1, 2011 FCC ID : WWGZ2200

Radiated emission



Rear view (below 1GHz)



UL Japan, Inc. Shonan EMC Lab.

1-22-3 Megumigaoka, Hiratsuka-shi, Kanagawa-ken, 259-1220 JAPAN


Telephone : +81 463 50 6400 Facsimile : +81 463 50 6401

Test report No.: 31FE0078-SH-01-A-R1

Page : 15 of 41 Issued date : August 1, 2011 FCC ID : WWGZ2200

Pre-check of the worst position

Antenna



UL Japan, Inc. Shonan EMC Lab.

1-22-3 Megumigaoka, Hiratsuka-shi, Kanagawa-ken, 259-1220 JAPAN


Telephone : +81 463 50 6400 Facsimile : +81 463 50 6401

Test report No.: 31FE0078-SH-01-A-R1

Page : 16 of 41

Issued date : August 1, 2011 FCC ID : WWGZ2200

Pre-check of the worst position



UL Japan, Inc. Shonan EMC Lab.

1-22-3 Megumigaoka, Hiratsuka-shi, Kanagawa-ken, 259-1220 JAPAN

Telephone : +81 463 50 6400 Facsimile : +81 463 50 6401