## 1. External Photograph of EUT

Brand Name: Razer / Model Name: RC30-004802

Report No.: EP092811-01



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: WX9RC30004802 IC: 8092A-RC30004802 Page Number : 1 of 18
Report Issued Date : Jan. 31, 2011
Report Version : Rev. 02



Brand Name: Razer / Model Name: RC30-004802

Report No.: EP092811-01



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: WX9RC30004802 IC: 8092A-RC30004802

Page Number : 2 of 18 Report Issued Date : Jan. 31, 2011 Report Version : Rev. 02

## 2. Photograph of Accessory

Brand Name: Razer / Model Name: RC30-004802

Report No.: EP092811-01

**List of Accessory:** 

Specification of Accessory		
Wireless Gaming	Brand Name	Razer
Headset	Model Name	RC30-004801
IAC Adanter	Brand Name	Razer
	Model Name	TS06X-2U050-0501D
RCA Line	Signal Line Type	1.0meter non-shielded cable without ferrite core
Optical Fiber Line	Signal Line Type	0.9meter non-shielded cable without ferrite core
Audio Cable	Signal Line Type	0.9meter non-shielded cable without ferrite core

**Remark:** For accessories equipped with this EUT, please refer to the following photos.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: WX9RC30004802 IC: 8092A-RC30004802 Page Number : 3 of 18 Report Issued Date : Jan. 31, 2011

Report Version : Rev. 02



Brand Name: Razer / Model Name: RC30-004802

Report No.: EP092811-01



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: WX9RC30004802 IC: 8092A-RC30004802

Page Number : 4 of 18 Report Issued Date : Jan. 31, 2011 Report Version : Rev. 02

Brand Name: Razer / Model Name: RC30-004802

Report No.: EP092811-01



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: WX9RC30004802 IC: 8092A-RC30004802 Page Number : 5 of 18
Report Issued Date : Jan. 31, 2011
Report Version : Rev. 02