

Appendix B. Setup Photographs

<Conducted Emission>




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: WX9RC30004702 Page Number : B1 of B2
Report Issued Date : Dec. 17, 2010
Report Version : Rev. 01

Report No.: FR092824-01




<Radiated Emission>

<Below 1GHz>



<Above 1GHz>



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: WX9RC30004702 Page Number : B2 of B2
Report Issued Date : Dec. 17, 2010
Report Version : Rev. 01

Report No.: FR092824-01