
3. Internal Photograph of EUT


Brand Name: Razer / Model Name: RC30-004702

Report No.: EP092824-01



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: WX9RC30004702 IC: 8092A-RC30004702 Page Number : 8 of 17 Report Issued Date : Dec. 17, 2010





SPORTON INTERNATIONAL INC.


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: WX9RC30004702 IC: 8092A-RC30004702 Page Number : 9 of 17 Report Issued Date : Dec. 17, 2010



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: WX9RC30004702 IC: 8092A-RC30004702

Page Number : 10 of 17 Report Issued Date : Dec. 17, 2010






08 04 09 05 04 05 02 01 001 06 08 04 09


SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: WX9RC30004702 IC: 8092A-RC30004702 Page Number : 11 of 17
Report Issued Date : Dec. 17, 2010
Report Version : Rev. 01

20




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: WX9RC30004702 IC: 8092A-RC30004702 Page Number : 12 of 17 Report Issued Date : Dec. 17, 2010



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: WX9RC30004702 IC: 8092A-RC30004702 Page Number : 13 of 17 Report Issued Date : Dec. 17, 2010






SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: WX9RC30004702 IC: 8092A-RC30004702 Page Number : 14 of 17
Report Issued Date : Dec. 17, 2010






SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: WX9RC30004702 IC: 8092A-RC30004702 Page Number : 15 of 17
Report Issued Date : Dec. 17, 2010
Report Version : Rev. 01



Report No.: EP092824-01




SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: WX9RC30004702 IC: 8092A-RC30004702

Page Number : 16 of 17 Report Issued Date : Dec. 17, 2010



Report No.: EP092824-01



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: WX9RC30004702 IC: 8092A-RC30004702

Page Number : 17 of 17 Report Issued Date : Dec. 17, 2010 Report Version : Rev. 01