

Appendix B. Setup Photographs

<Conducted Emission>



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: WX9RC30004701 Page Number : B1 of B2
Report Issued Date : Dec. 17, 2010
Report Version : Rev. 01


Report No.: FR092824



Report No.: FR092824

<Radiated Emission>

<Below 1GHz>



<Above 1GHz>



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: WX9RC30004701 Page Number : B2 of B2 Report Issued Date: Dec. 17, 2010 Report Version : Rev. 01