1. External Photograph of EUT

Brand Name: Razer / Model Name: RC30-004702

Report No.: EP092824-01




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: WX9RC30004702 IC: 8092A-RC30004702

: Rev. 01

Report Version



Report No.: EP092824-01



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: WX9RC30004702 IC: 8092A-RC30004702

Page Number : 2 of 17 Report Issued Date : Dec. 17, 2010

Report Version : Rev. 01

2. Photograph of Accessory

Brand Name: Razer / Model Name: RC30-004702

Report No.: EP092824-01

List of Accessory:

Specification of Accessory		
AC Adapter	Brand Name	Razer
(for Dock)	Model Name	TS06X-2U050-0501D
	Brand Name	Razer
	Model Name	RC30-004701
	Brand Name	NA
	Model Name	NA
	Brand Name	NA
	Model Name	NA

Remark: For accessories equipped with this EUT, please refer to the following photos.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: WX9RC30004702 IC: 8092A-RC30004702 Page Number : 3 of 17 Report Issued Date : Dec. 17, 2010

Report Version : Rev. 01

Report No.: EP092824-01



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: WX9RC30004702 IC: 8092A-RC30004702 Page Number : 4 of 17

Report Issued Date : Dec. 17, 2010 Report Version : Rev. 01

Report No.: EP092824-01

Brand Name: Razer / Model Name: RC30-004702



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: WX9RC30004702 IC: 8092A-RC30004702 Page Number : 5 of 17 Report Issued Date : Dec. 17, 2010

Report Version : Rev. 01



Report No.: EP092824-01



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: WX9RC30004702 IC: 8092A-RC30004702

Page Number : 6 of 17

Report Issued Date : Dec. 17, 2010 Report Version : Rev. 01



Report No.: EP092824-01



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: WX9RC30004702 IC: 8092A-RC30004702

Page Number : 7 of 17 Report Issued Date : Dec. 17, 2010

: Rev. 01

Report Version