
3. Internal Photograph of EUT

Brand Name: Razer / Model Name: RC30-004701


Report No.: EP092824



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: WX9RC30004701 IC: 8092A-RC30004701 Page Number : 9 of 19 Report Issued Date : Dec. 17, 2010

Report Version : Rev. 01






TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: WX9RC30004701 IC: 8092A-RC30004701

Page Number : 10 of 19 Report Issued Date : Dec. 17, 2010 Report Version : Rev. 01

Report No.: EP092824




Report No.: EP092824



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: WX9RC30004701 IC: 8092A-RC30004701

Page Number : 11 of 19 Report Issued Date : Dec. 17, 2010 Report Version : Rev. 01




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: WX9RC30004701 IC: 8092A-RC30004701

Page Number : 12 of 19 Report Issued Date : Dec. 17, 2010 Report Version : Rev. 01

Report No.: EP092824






TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: WX9RC30004701 IC: 8092A-RC30004701

Page Number : 13 of 19 Report Issued Date : Dec. 17, 2010

Report No.: EP092824

Report Version : Rev. 01






TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: WX9RC30004701 IC: 8092A-RC30004701

Page Number : 14 of 19 Report Issued Date : Dec. 17, 2010 Report Version : Rev. 01

Report No.: EP092824



Report No.: EP092824




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: WX9RC30004701 IC: 8092A-RC30004701

Page Number : 15 of 19 Report Issued Date : Dec. 17, 2010 Report Version : Rev. 01



Report No.: EP092824




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: WX9RC30004701 IC: 8092A-RC30004701

Page Number : 16 of 19 Report Issued Date : Dec. 17, 2010 Report Version : Rev. 01



Report No.: EP092824




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: WX9RC30004701 IC: 8092A-RC30004701

Page Number : 17 of 19 Report Issued Date : Dec. 17, 2010

Report Version : Rev. 01



Report No.: EP092824



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: WX9RC30004701 IC: 8092A-RC30004701

: 18 of 19 Page Number Report Issued Date : Dec. 17, 2010 Report Version : Rev. 01

Page Number

Report Version

: 19 of 19

: Rev. 01

Report Issued Date : Dec. 17, 2010

Report No.: EP092824



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: WX9RC30004701 IC: 8092A-RC30004701