


8 EUT TEST PHOTO

Conducted emission test photos MP90AR





Report No.: BTL-FCCP-1-1603241 Page 21 of 81



MP90AR






Report No.: BTL-FCCP-1-1603241 Page 22 of 81



MP90AL






Report No.: BTL-FCCP-1-1603241 Page 23 of 81



MP90AU






Report No.: BTL-FCCP-1-1603241 Page 24 of 81



MP90AH






Report No.: BTL-FCCP-1-1603241 Page 25 of 81



Radiated emission test photos 9KHz to 30MHz MP90AR





Report No.: BTL-FCCP-1-1603241 Page 26 of 81



MP90AR







Report No.: BTL-FCCP-1-1603241 Page 27 of 81



MP90AL







Report No.: BTL-FCCP-1-1603241 Page 28 of 81



MP90AU







Report No.: BTL-FCCP-1-1603241 Page 29 of 81



MP90AH







Report No.: BTL-FCCP-1-1603241 Page 30 of 81



Radiated emission test photos 30MHz to 1000MHz MP90AR







Report No.: BTL-FCCP-1-1603241 Page 31 of 81



MP90AR






Report No.: BTL-FCCP-1-1603241 Page 32 of 81



MP90AL







Report No.: BTL-FCCP-1-1603241 Page 33 of 81



MP90AU






Report No.: BTL-FCCP-1-1603241 Page 34 of 81



MP90AH





Report No.: BTL-FCCP-1-1603241 Page 35 of 81