


Appendix D. Product Photos

DUT: 802.11n 1x1 PCIe Minicard Transceiver (Model Name: AR5B95)




Host: Notebook Personal Computer (Model: FT20)



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: WXC-T77H121050 Page Number : D1 of D6
Report Issued Date : Mar. 22, 2010
Report Version : Rev. 01






SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: WXC-T77H121050 Page Number : D2 of D6
Report Issued Date : Mar. 22, 2010
Report Version : Rev. 01



FCC SAR Test Report



Host: Notebook Personal Computer (Model: FT30)




SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: WXC-T77H121050 Page Number : D3 of D6
Report Issued Date : Mar. 22, 2010
Report Version : Rev. 01



FCC SAR Test Report




SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: WXC-T77H121050

: D4 of D6 Page Number Report Issued Date: Mar. 22, 2010 Report Version : Rev. 01



FCC SAR Test Report




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: WXC-T77H121050 Page Number : D5 of D6
Report Issued Date : Mar. 22, 2010
Report Version : Rev. 01



Report No.: FA010835

Antenna Location:



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: WXC-T77H121050 Page Number : D6 of D6
Report Issued Date : Mar. 22, 2010
Report Version : Rev. 01



Appendix E. Test Setup Photos



Bottom with the Host (FT20) with Phantom 0 cm Bottom with the Host (FT30) with Phantom 0 cm Gap

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: WXC-T77H121050 Page Number : E1 of E1
Report Issued Date : Mar. 22, 2010
Report Version : Rev. 01