## 2. Internal Photograph of EUT

Brand Name: Distracted Driving Device / Model Name: DDD-1 / Marketing Name: DDD




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: WXT-DDD1RX IC: 8098A-DDD1RX Page Number : 7 of 15 Report Issued Date : Sep. 11, 2017

Report No.: EP772705

Report Version : Rev. 01


Report No.: EP772705




SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: WXT-DDD1RX IC: 8098A-DDD1RX Page Number : 8 of 15
Report Issued Date : Sep. 11, 2017


Report Version : Rev. 01



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: WXT-DDD1RX IC: 8098A-DDD1RX Page Number : 9 of 15
Report Issued Date : Sep. 11, 2017
Report Version : Rev. 01




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: WXT-DDD1RX IC: 8098A-DDD1RX Page Number : 10 of 15
Report Issued Date : Sep. 11, 2017
Report Version : Rev. 01




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: WXT-DDD1RX IC: 8098A-DDD1RX Page Number : 11 of 15
Report Issued Date : Sep. 11, 2017
Report Version : Rev. 01





TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: WXT-DDD1RX IC: 8098A-DDD1RX Page Number : 12 of 15
Report Issued Date : Sep. 11, 2017
Report Version : Rev. 01






TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: WXT-DDD1RX IC: 8098A-DDD1RX

Page Number : 13 of 15 Report Issued Date : Sep. 11, 2017 Report Version : Rev. 01






TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: WXT-DDD1RX IC: 8098A-DDD1RX

Page Number : 14 of 15 Report Issued Date : Sep. 11, 2017

Report No.: EP772705

Report Version : Rev. 01





TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: WXT-DDD1RX IC: 8098A-DDD1RX

Page Number : 15 of 15 Report Issued Date : Sep. 11, 2017 Report Version : Rev. 01