

2. Internal Photograph of EUT

Brand Name: Distracted Driving Device / Model Name: DDD-1 / Marketing Name: DDD




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: WXT-DDD1RX IC: 8098A-DDD1RX Page Number : 7 of 15
Report Issued Date : Dec. 07, 2017
Report Version : Rev. 01

Report No.: EP772705-01



SPORTON INTERNATIONAL INC.


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: WXT-DDD1RX IC: 8098A-DDD1RX Page Number : 8 of 15
Report Issued Date : Dec. 07, 2017
Report Version : Rev. 01



Page Number : 9 of 15
Report Issued Date : Dec. 07, 2017
Report Version : Rev. 01


Report No.: EP772705-01

Brand Name: Distracted Driving Device / Model Name: DDD-1 / Marketing Name: DDD




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: WXT-DDD1RX IC: 8098A-DDD1RX Page Number : 10 of 15
Report Issued Date : Dec. 07, 2017
Report Version : Rev. 01

Report No.: EP772705-01




SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: WXT-DDD1RX IC: 8098A-DDD1RX Page Number : 11 of 15
Report Issued Date : Dec. 07, 2017
Report Version : Rev. 01




Page Number : 12 of 15
Report Issued Date : Dec. 07, 2017
Report Version : Rev. 01



SPORTON INTERNATIONAL INC.


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: WXT-DDD1RX IC: 8098A-DDD1RX Page Number : 13 of 15
Report Issued Date : Dec. 07, 2017
Report Version : Rev. 01





Page Number : 14 of 15
Report Issued Date : Dec. 07, 2017
Report Version : Rev. 01





Page Number : 15 of 15
Report Issued Date : Dec. 07, 2017
Report Version : Rev. 01