Test report No. : 11343921H-A-R2
Page : 58 of 61
Issued date : October 21, 2016
FCC ID : WY7-TYPE1FJ

APPENDIX 3: Photographs of test setup

Conducted Emission




Photo 1




Photo 2

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone: +81 596 24 8999 Facsimile: +81 596 24 8124

: 11343921H-A-R2 Test report No. Page : 59 of 61

Issued date : October 21, 2016 FCC ID : WY7-TYPE1FJ

Radiated Spurious Emission (Below 1GHz)



Photo 1



Photo 2

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone: +81 596 24 8999 Facsimile : +81 596 24 8124

: 11343921H-A-R2 Test report No. Page : 60 of 61 Issued date : October 21, 2016 FCC ID : WY7-TYPE1FJ

Radiated Spurious Emission (Above 1GHz)



Photo 1



Photo 2

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone: +81 596 24 8999 Facsimile : +81 596 24 8124

Test report No. : 11343921H-A-R2
Page : 61 of 61
Issued date : October 21, 2016
FCC ID : WY7-TYPE1FJ

Worst Case Position


WLAN

Below 1GHz (Horizontal: Z-axis/ Vertical: X-axis) Above 1GHz (Horizontal: Z-axis/ Vertical: Z-axis)


BTLE

Below 1GHz (Horizontal: X-axis/ Vertical: X-axis) Above 1GHz (Horizontal: X-axis/ Vertical: Z-axis)






Y-axis



Z-axis



End of Report

UL Japan, Inc. Ise EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone: +81 596 24 8999 Facsimile: +81 596 24 8124