Appendix A. Setup Photographs

<AC Conducted Emission>

Mode 4





Sporton International (Kunshan) Inc.

TEL: +86-512-57900158 FAX: +86-512-57900958 FCC ID: WYPPG2132 Page Number : A1 of A3
Report Issued Date : Dec. 04, 2017
Report Version : Rev. 01

Report Template No.: BU5-FC15B Version 1.3

Report No.: FC792101-01

C Test Report No. : FC792101-01

Mode 6





Sporton International (Kunshan) Inc.


TEL: +86-512-57900158 FAX: +86-512-57900958 FCC ID: WYPPG2132 Page Number : A2 of A3
Report Issued Date : Dec. 04, 2017
Report Version : Rev. 01

Report Template No.: BU5-FC15B Version 1.3


<Radiated Emission>

Mode 5

LF



HF



Sporton International (Kunshan) Inc.

TEL: +86-512-57900158 FAX: +86-512-57900958 FCC ID: WYPPG2132 Page Number : A3 of A3
Report Issued Date : Dec. 04, 2017
Report Version : Rev. 01

Report Template No.: BU5-FC15B Version 1.3

Report No.: FC792101-01