


Report No. : FR792101E

## Appendix D. Setup Photographs

## <Conducted Emission>





Sporton International (Kunshan) Inc.

TEL: +86-512-57900158 FAX: +86-512-57900958 FCC ID: WYPPC2100 Page Number : D1 of D2
Report Issued Date : Dec. 04, 2017
Report Version : Rev. 01


Report Template No.: BU5-FR15EWLB4 AC MA Version 1.5




## <Radiated Emission>

X Plane

LF



HF



Sporton International (Kunshan) Inc.

TEL: +86-512-57900158 FAX: +86-512-57900958 FCC ID: WYPPC2100 Page Number : D2 of D2
Report Issued Date : Dec. 04, 2017
Report Version : Rev. 01

Report No.: FR792101E

Report Template No.: BU5-FR15EWLB4 AC MA Version 1.5