

11. SETUP PHOTOS


11.1. ANTENNA PORT CONDUCTED RF MEASUREMENT SETUP



11.2. RADIATED RF WORST CASE PHOTO SETUP


11.2.1. LINEARLY POLARIZED & CIRCULARLY POLARIZED PATCH **ANTENNAS**







Page 86 of 97


11.2.2. **DIPOLE ANTENNA**






11.2.3. **PIFA ANTENNA**









RADIATED RF MEASUREMENT SETUP (BELOW 1 GHz) 11.3.


11.3.1. LINEARLY POLARIZED PATCH ANTENNA







CIRCULARLY POLARIZED PATCH ANTENNA 11.3.2.






11.3.3. **DIPOLE ANTENNA**






11.3.4. **PIFA ANTENNA**






RADIATED RF MEASUREMENT SETUP (ABOVE 1 GHz) 11.4.


11.4.1. LINEARLY POLARIZED & CIRCULARLY POLARIZED PATCH **ANTENNAS**







Page 94 of 97


11.4.2. **DIPOLE ANTENNA**






11.4.3. **PIFA ANTENNA**





11.5. POWERLINE CONDUCTED EMISSIONS MEASUREMENT SETUP





END OF REPORT

Page 97 of 97