Report No. : HS1303150050A-1

Version : E



SALT SPRAY TEST REPORT

Company : <u>Alltek Marine Electronics Corp.</u>

Address : <u>7F, No. 605, Ruei Guang Rd., Neihu Dist., Taipei 114,</u>

Taiwan, R.O.C.

Sample Name : AIS Class B Transponder

Date Received : MAR 15, 2013

Date Tested : MAR 15, 2013 ~ APR 12, 2013

TESTING LABORATORY IS ACCREDITED BY:

IEC/IECQ 17025 certificate of independent test laboratory approval

Certificate No.: 1.72.0031

ISO 17025 accredited in respect of laboratory is approved by TAF

Certificate No.: L0835-120910

ISO 9001 certificate is approved by TUV CERT certification body of TUV NORD Cert GmbH

WE HEREBY CERTIFY THAT:

The test(s) shown in the attachment were conducted according to the indicating procedures. We assume full responsibility for the accuracy and completeness of these tests and vouch for the qualifications of all personnel performing them.

| 00-40-5-1 | Name | Signature | Date |
|---------------|-------------|-------------|--------------|
| Test Engineer | Gin Lu | Fin Lu | Oct 30, 2013 |
| Manager | Longson Lin | Longson Lin | Oct 30, 2013 |


NOTE:

1. This report will be invalid if reproduced in part or altered in any way.

2. This report refers only to the specimen(s) submitted to test, and is invalid if used otherway

3. This report is ONLY valid with the examination seal and signature of this institute

4. The tested specimen(s) will only be preserved for thirty days from the date is collected by the applicant.



INTEGRATED SERVICE TECHNOLOGY

REVISIONS HISTORY

| Rev. | Issue Date | Revisions | Effect page |
|------|------------------|---|-------------|
| Α | April 24, 2013 | Initial issre | All |
| В | April 25, 2013 | Correct typo at Section 1.1 | 2 |
| С | June 25, 2013 | Modify software version at Section 1.1 | 2 |
| D | July 09, 2013 | Modify Multi-list information at Section 1.1 | 2 |
| Е | October 30, 2013 | Add Revisions History Add edition number and publish year at Section 2.3 | 3 |



Reliability & Failure Analysis Engineering Group 1F, No.19, Pu-ding Rd., Hsin - chu City, Taiwan, R.O.C.

Tel: 886-3-579-9909, Fax: 886-3-610-0399

http://www.istgroup.com

Report No.: HS1303150050A-1

Page 1 of 17

TABLE OF CONTENTS

| 1. GENERAL INFORMATION | |
|-----------------------------------|---|
| 1.1 DESCRIPTION OF UNIT | 2 |
| 1.2 UNIT OPERATING CONDITION | 2 |
| 2. SALT SPRAY TEST | |
| 2.1 TEST EQUIPMENT | 3 |
| 2.2 LABORATORY AMBIENCE CONDITION | 3 |
| 2.3 REFERENCE DOCUMENT | 3 |
| 2.4 TEST CONDITION | 3 |
| 2.5 SUMMARY OF TEST | 3 |
| ATTACUMENTS | 1 |



Reliability & Failure Analysis Engineering Group 1F, No.19, Pu-ding Rd., Hsin - chu City, Taiwan, R.O.C.

Tel: 886-3-579-9909, Fax: 886-3-610-0399

http://www.istgroup.com

Report No.: HS1303150050A-1

Page 2 of 17

1. GENERAL INFORMATION

1.1 DESCRIPTION OF UNIT

Manufacturer: Alltek Marine Electronics Corp.

Sample name: AIS Class B Transponder

Model name : CAMINO-108W Hardware : M-PCB-B108MBV1

Software: V1.2.6


Sample quantity: 1 unit

Multi-list information:

| Multi-list | Difference within models |
|-------------|------------------------------------|
| CAMINO-108W | AIS Class B Transponder with Wi-Fi |
| CAMINO-108 | AIS Class B Transponder |

Note: This information is provided by the Alltek Marine Electronics Corp.

1.2 UNIT OPERATING CONDITION:



| | EUT Cable Type | Signal Cable Description |
|---|-----------------------|--------------------------|
| Α | VHF cable | Shielded, 10m |
| В | GPS cable | Shielded, 10m |
| С | Mini USB to USB cable | Shielded, 1.8m |
| D | NMEA 2000 Cable | Shielded, 0.6m |
| Е | Power/Data cable | Shielded, 1.4m |



Reliability & Failure Analysis Engineering Group 1F, No.19, Pu-ding Rd., Hsin - chu City, Taiwan, R.O.C.

Tel: 886-3-579-9909, Fax: 886-3-610-0399

http://www.istgroup.com

Report No.: HS1303150050A-1

Page 3 of 17

2. SALT SPRAY TEST

2.1 TEST EQUIPMENT

| Model | Serial Number | Calibration Date |
|--------------------------------|----------------|------------------|
| Vötsch VSC/KWT 1000 | 59566059630010 | NOV. 12, 2012 |
| THERMOTRON SM-32-7800 (USA) | 34381 | MAR. 08, 2012 |

2.2 LABORATORY AMBIENCE CONDITION

Temperature: 23 ± 3 °C

Relative humidity: 55 % ± 3 % (RH)

2.3 REFERENCE DOCUMENT

The test based on IEC 60068-2-52 severity 1 (Second edition 1996-01)

2.4 TEST CONDITION

2.4.1 Salt spray

Units are non-operating.

Test temperature: 35°C

Concentration: Salt solution concentration is at 5 ±1% of salt. The solution is prepared by dissolving 5 ±1%

of salt in 95% of distilled water. The measurement is based on the weight of salt.

Salt solution pH value : 6.5 ~ 7.2 at temperature 25°C±2°C

Salt deposit rate: 1~2 mls/80 cm²/hr

2.4.2 Temp./Humidity storage

Place the unit into the temperature chamber

Test temperature storage : 40°C
Test Humidity storage : 93% (RH)

Test cycle: Dwell for 2 hours at the salt spray; Dwell for 6days and 22 hours at the humidity storage

Number of cycles: 4 cycles

2.5 SUMMARY OF TEST

After testing, visual inspection showed corrosion trace on the unit, but unit function was normal.



Reliability & Failure Analysis Engineering Group 1F, No.19, Pu-ding Rd., Hsin - chu City, Taiwan, R.O.C.

Tel: 886-3-579-9909, Fax: 886-3-610-0399

http://www.istgroup.com

Attachment 1: Photo of units before salt spray test





Report No.: HS1303150050A-1

Page 4 of 17











Reliability & Failure Analysis Engineering Group 1F, No.19, Pu-ding Rd., Hsin - chu City, Taiwan, R.O.C.

Report No.: HS1303150050A-1

Page 5 of 17

Tel: 886-3-579-9909, Fax: 886-3-610-0399


http://www.istgroup.com

Attachment 2: Photo of salt spray test setup

Salt spray



Temp./Humidity storage





Reliability & Failure Analysis Engineering Group 1F, No.19, Pu-ding Rd., Hsin - chu City, Taiwan, R.O.C.


Tel: 886-3-579-9909, Fax: 886-3-610-0399

http://www.istgroup.com

Report No.: HS1303150050A-1

Page 6 of 17

Attachment 3: Photo of units after salt spray test





Reliability & Failure Analysis Engineering Group 1F, No.19, Pu-ding Rd., Hsin - chu City, Taiwan, R.O.C.

Tel: 886-3-579-9909, Fax: 886-3-610-0399

http://www.istgroup.com

Report No.: HS1303150050A-1

Page 7 of 17

Unit appearance

After testing (No cleaning)















Reliability & Failure Analysis Engineering Group 1F, No.19, Pu-ding Rd., Hsin - chu City, Taiwan, R.O.C.

Tel: 886-3-579-9909, Fax: 886-3-610-0399

http://www.istgroup.com

Report No.: HS1303150050A-1

Page 8 of 17

Unit appearance

After testing (No cleaning)















Reliability & Failure Analysis Engineering Group 1F, No.19, Pu-ding Rd., Hsin - chu City, Taiwan, R.O.C.

Tel: 886-3-579-9909, Fax: 886-3-610-0399

http://www.istgroup.com

Unit appearance


Report No.: HS1303150050A-1

Page 9 of 17

After testing (No cleaning)









Reliability & Failure Analysis Engineering Group 1F, No.19, Pu-ding Rd., Hsin - chu City, Taiwan, R.O.C.

Tel: 886-3-579-9909, Fax: 886-3-610-0399

http://www.istgroup.com

Report No.: HS1303150050A-1

Page 10 of 17

Unit appearance


After testing (No cleaning)















Reliability & Failure Analysis Engineering Group 1F, No.19, Pu-ding Rd., Hsin - chu City, Taiwan, R.O.C.

Tel: 886-3-579-9909, Fax: 886-3-610-0399

http://www.istgroup.com

Report No.: HS1303150050A-1


Page 11 of 17

Unit appearance

After testing (No cleaning)











Reliability & Failure Analysis Engineering Group 1F, No.19, Pu-ding Rd., Hsin - chu City, Taiwan, R.O.C.

Tel: 886-3-579-9909, Fax: 886-3-610-0399

http://www.istgroup.com

Report No.: HS1303150050A-1

Page 12 of 17

Unit appearance

After testing (No cleaning)















Reliability & Failure Analysis Engineering Group 1F, No.19, Pu-ding Rd., Hsin - chu City, Taiwan, R.O.C.

Tel: 886-3-579-9909, Fax: 886-3-610-0399

http://www.istgroup.com


Unit appearance

Report No.: HS1303150050A-1

Page 13 of 17

After testing (No cleaning)









Reliability & Failure Analysis Engineering Group 1F, No.19, Pu-ding Rd., Hsin - chu City, Taiwan, R.O.C.

Tel: 886-3-579-9909, Fax: 886-3-610-0399

http://www.istgroup.com

Report No.: HS1303150050A-1

Page 14 of 17

Unit appearance


After cleaning


Showed corrosion trace on the unit















Reliability & Failure Analysis Engineering Group 1F, No.19, Pu-ding Rd., Hsin - chu City, Taiwan, R.O.C.

Tel: 886-3-579-9909, Fax: 886-3-610-0399

http://www.istgroup.com

Report No.: HS1303150050A-1

Page 15 of 17

Unit appearance

After cleaning


Showed corrosion trace on the unit
















Reliability & Failure Analysis Engineering Group 1F, No.19, Pu-ding Rd., Hsin - chu City, Taiwan, R.O.C. Tel: 886-3-579-9909, Fax: 886-3-610-0399

http://www.istgroup.com

Report No.: HS1303150050A-1

Page 16 of 17

Unit appearance

After cleaning

Showed corrosion trace on the unit







Reliability & Failure Analysis Engineering Group 1F, No.19, Pu-ding Rd., Hsin - chu City, Taiwan, R.O.C.

Tel: 886-3-579-9909, Fax: 886-3-610-0399

http://www.istgroup.com

Page 17 of 17

Report No.: HS1303150050A-1

Attachment 4: Graph of temp./humidity storage test

