3. Internal Photograph of EUT


Model Name: W800

Report No.: EP9D2523




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: X4BLQAM350 Page Number : 15 of 33
Issued Date : Jan. 15, 2010
Report Version : Rev. 01

Report No.: EP9D2523




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: X4BLQAM350 Page Number : 16 of 33
Issued Date : Jan. 15, 2010
Report Version : Rev. 01

Report No.: EP9D2523




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: X4BLQAM350 Page Number : 17 of 33
Issued Date : Jan. 15, 2010
Report Version : Rev. 01

Report No.: EP9D2523




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: X4BLQAM350 Page Number : 18 of 33 Issued Date : Jan. 15, 2010 Report Version : Rev. 01

Report No.: EP9D2523




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: X4BLQAM350 Page Number : 19 of 33 Issued Date : Jan. 15, 2010 Report Version : Rev. 01

Report No.: EP9D2523




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: X4BLQAM350 Page Number : 20 of 33 Issued Date : Jan. 15, 2010 Report Version : Rev. 01

Report No.: EP9D2523




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: X4BLQAM350 Page Number : 21 of 33 Issued Date : Jan. 15, 2010 Report Version : Rev. 01

Report No.: EP9D2523




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: X4BLQAM350 Page Number : 22 of 33 Issued Date : Jan. 15, 2010 Report Version : Rev. 01

Report No.: EP9D2523




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: X4BLQAM350 Page Number : 23 of 33 Issued Date : Jan. 15, 2010 Report Version : Rev. 01

Report No.: EP9D2523



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: X4BLQAM350 Page Number : 24 of 33
Issued Date : Jan. 15, 2010
Report Version : Rev. 01

Report No.: EP9D2523




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: X4BLQAM350 Page Number : 25 of 33
Issued Date : Jan. 15, 2010
Report Version : Rev. 01

Report No.: EP9D2523




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: X4BLQAM350 Page Number : 26 of 33 : Jan. 15, 2010 Issued Date Report Version : Rev. 01

Report No.: EP9D2523




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: X4BLQAM350 Page Number : 27 of 33
Issued Date : Jan. 15, 2010
Report Version : Rev. 01

Report No.: EP9D2523



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: X4BLQAM350 Page Number : 28 of 33
Issued Date : Jan. 15, 2010
Report Version : Rev. 01



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: X4BLQAM350 Page Number : 29 of 33
Issued Date : Jan. 15, 2010
Report Version : Rev. 01

Report No.: EP9D2523

Report No.: EP9D2523



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: X4BLQAM350 Page Number : 30 of 33 Issued Date : Jan. 15, 2010 Report Version : Rev. 01

Report No.: EP9D2523




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: X4BLQAM350 Page Number : 31 of 33
Issued Date : Jan. 15, 2010
Report Version : Rev. 01

Report No.: EP9D2523



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: X4BLQAM350 Page Number : 32 of 33 Issued Date : Jan. 15, 2010 Report Version : Rev. 01

Report No.: EP9D2523



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: X4BLQAM350 Page Number : 33 of 33 Issued Date : Jan. 15, 2010 Report Version : Rev. 01