

January 9, 2017

Attestation

Subject: Attestation of disabled 40 MHz Bandwidth operation

FCC ID: X4G-S00146

Although the Broadcom BCM43340 chipset features both 20 MHz and 40 MHz bandwidth operation for WiFi, the Axon Flex 2 camera system, FCC ID X4G-S00146 does not use the 40 MHz bandwidth feature and does not allow the user to access to that feature. The feature is disabled in the operating firmware of the camera and can only be accessed using engineering tools, that are not available to the user.

Sincerely,

Bryan Chiles / Technical Compliance Manager

480-502-6260 (Direct)

bchiles@taser.com