Test report No.
 : 12069762H-A-R1

 Page
 : 44 of 45

 Issued date
 : November 20, 2018

 FCC ID
 : X4QKDTG200

APPENDIX 3: Photographs of test setup

Radiated Spurious Emission




Photo 1




Photo 2

UL Japan, Inc. Kashima EMC Lab.


1614, Mushihata, Katori-shi, Chiba-ken, 289-0341 Japan

Telephone: +81 478 88 6500 Facsimile: +81 478 82 3373

Test report No. : 12069762H-A-R1
Page : 45 of 45
Issued date : November 20, 2018
FCC ID : X4QKDTG200

Worst Case Position

Below 1 GHz (Horizontal: X-axis/ Vertical: X-axis) Above 1 GHz (Horizontal: Z-axis/ Vertical: Y-axis)







End of Report

1614, Mushihata, Katori-shi, Chiba-ken, 289-0341 Japan

Telephone: +81 478 88 6500 Facsimile: +81 478 82 3373