





FCC ID: X5Y775-1089-01 Product Name: BSNode-870/2 C TS

Tune up Informations

No tune up procedure is required by technician or user after the equipment has left the factory to match its specifications on the working frequency.

The BSNode-870 has no manual trimmers or adjustments that can be manually done on it acting directly on the BSNode itself.

08/03/2012 codice tecnico 1