

UL Korea, Ltd

www.ulk.co.kr

Project: 10CA05635

File: TC8389

Report 10CA05635-FCC Date: March 10, 2010

Model: FireCR (Basic) and VetCR

Test setup Photo

For

Computed Radiography Scanner

3D Imaging & Simulations Corp. 49-3, Moonpyung-Dong, Daedeok-Gu, Daejeon, Korea

Copyright © 2005 Underwriters Laboratories Inc.


33rdFl. Gangnam finance Center, 737 Yeoksam-Dong, Kangnam-Gu, Seoul, 135-984, Korea Underwriters Laboratories Inc. authorizes the above-named company to reproduce this Report provided it is reproduced in its entirety.


UL Korea, Ltd 33rd FL, Gangnam Finance Center, 737 Yeoksam-dong, Gangnam-gu, Seoul 135-984 Korea

Tel: +82.2.2009.9000, Fax:+82.2.2009.9405

A not-for-profit organization dedicated to public safety and committed to quality service for over 100 years Project Number: 10CA05635 File Number TC8389 Test Report No: 10CA05635-FCC Model Number: FireCR Date of Issue: March 10, 2010

Figure 1. Conducted Emission Test Setup





Project Number: 10CA05635 File Number TC8389 Test Report No: 10CA05635-FCC Model Number: FireCR Date of Issue: March 10, 2010

Figure 2, Photo of Radiated emission test setup

