


page 1 of 5

# Annex A Test setup photos




161065\_ST1.JPG: FPS COM 7000, test setup fully anechoic chamber



page 2 of 5

# Annex A Test setup photos




161065\_ST2.JPG: FPS COM 7000, test setup fully anechoic chamber



page 3 of 5

# Annex A Test setup photos




161065\_ST3.JPG: FPS COM 7000, test setup fully anechoic chamber



page 4 of 5

### Annex A Test setup photos




161065\_ST4.JPG: FPS COM 7000, test setup fully anechoic chamber



page 5 of 5

### **Test setup photos** Annex A



161065\_ST5.JPG: FPS COM 7000, test setup fully anechoic chamber

Examiner: Manuel BASTERT Date of issue: 08/24/2016 Test Report No.: F161065E8 Order No.: F161065E8