




151497_n_a.JPG: FPS COM 7000, test setup fully anechoic chamber

 Test engineer:
 Thomas KÜHN
 Report Number:
 F151497E8

 Date of issue:
 12/17/2015
 Order Number:
 15-111497
 page 1 of 6





151497_n_i.JPG: FPS COM 7000, test setup fully anechoic chamber

 Test engineer:
 Thomas KÜHN
 Report Number:
 F151497E8

 Date of issue:
 12/17/2015
 Order Number:
 15-111497

 page 2 of 6
 page 2 of 6






151497_n_f.JPG: FPS COM 7000, test set-up fully anechoic chamber

 Test engineer:
 Thomas KÜHN
 Report Number:
 F151497E8

 Date of issue:
 12/17/2015
 Order Number:
 15-111497

 page 3 of 6
 page 3 of 6






151497_n_b.JPG: FPS COM 7000, test set-up fully anechoic chamber

 Test engineer:
 Thomas KÜHN
 Report Number:
 F151497E8

 Date of issue:
 12/17/2015
 Order Number:
 15-111497

 page 4 of 6
 page 4 of 6






151497_n_e.JPG: FPS COM 7000, test set-up fully anechoic chamber

 Test engineer:
 Thomas KÜHN
 Report Number:
 F151497E8

 Date of issue:
 12/17/2015
 Order Number:
 15-111497

 page 5 of 6
 page 5 of 6





151497_n_j.JPG: FPS COM 7000, test set-up open area test site

 Test engineer:
 Thomas KÜHN
 Report Number:
 F151497E8

 Date of issue:
 12/17/2015
 Order Number:
 15-111497
 page 6 of 6