## **Correspondence by Project**

## **Project Number:**

1585310876

Correspondence Number	Memo
X74WWG1F418-1	1) The block diagram submitted is not sufficient. As per section 2.1033(b)(5) of the FCC rules, the block diagram must show "the frequency of all oscillators used in the device. The signal path and frequency shall be indicated at each block. The tuning range(s) and intermediate frequency(ies) shall be indicated at each block." Response: The block diagram has been revised to show the oscillators and intermediate frequencies. 2) Please include complete internal photos of the EUT. There is no photo of the area underneath the battery holder. Response: The internal photos have been revised to show the are underneath the battery holder. 3) For the operational description, please provide the data sheet that was mentioned. Response: The data sheet has been uploaded. 4) Please provide a plot showing the device ceasing transmission within five seconds of activation. Response: The test report has been revised to include the plot showing the device ceases transmission within 5 second.