


Report No.: FR2N0915C

Appendix B. Setup Photographs

<Conducted Emission>



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: X7H-SH837WI Page Number : B1 of B2
Report Issued Date : Dec. 10, 2012
Report Version : Rev. 01




Report No. : FR2N0915C

<Radiated Emission>

LF



HF



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: X7H-SH837WI Page Number : B2 of B2
Report Issued Date : Dec. 10, 2012
Report Version : Rev. 01