



Appendix B. Setup Photographs

<Conducted Emission>

Mode 2



Front View




Rear View

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: X7H-N700 Page Number : B1 of B4
Report Issued Date : Nov. 04, 2010
Report Version : Rev. 01








Side View

SPORTON INTERNATIONAL INC.


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: X7H-N700 Page Number : B2 of B4
Report Issued Date : Nov. 04, 2010
Report Version : Rev. 01



<Radiated Emission>



Front View



Rear View

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: X7H-N700 Page Number : B3 of B4
Report Issued Date : Nov. 04, 2010
Report Version : Rev. 01







Remote View

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: X7H-N700 Page Number : B4 of B4
Report Issued Date : Nov. 04, 2010
Report Version : Rev. 01