


## Appendix B. Setup Photographs

## <Conducted Emission>



Front View



Rear View

SPORTON INTERNATIONAL INC.


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: X7H-F800 Page Number : B1 of B4
Report Issued Date : Apr. 21, 2010

Report No.: FR020335B

Report Version : Rev. 01







Report No.: FR020335B

Side View

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: X7H-F800 Page Number : B2 of B4
Report Issued Date : Apr. 21, 2010
Report Version : Rev. 01





Report No.: FR020335B

## <Radiated Emission>



Front View



Rear View

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: X7H-F800

Page Number : B3 of B4 Report Issued Date: Apr. 21, 2010 Report Version : Rev. 01





Report No.: FR020335B



Remote View

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: X7H-F800 Page Number : B4 of B4
Report Issued Date : Apr. 21, 2010
Report Version : Rev. 01