


## Test Report No. : FR020335A

## Appendix B. Setup Photographs

## <Conducted Emission>



Front View



Rear View

SPORTON INTERNATIONAL INC.


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: X7H-F800 Page Number : B1 of B4
Report Issued Date : Apr. 21, 2010

Report Version : Rev. 01





Report No.: FR020335A



Side View

SPORTON INTERNATIONAL INC.


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: X7H-F800 Page Number : B2 of B4
Report Issued Date : Apr. 21, 2010
Report Version : Rev. 01






Report No. : FR020335A

## <Radiated Emission>



Front View



Rear View

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: X7H-F800 Page Number : B3 of B4
Report Issued Date : Apr. 21, 2010
Report Version : Rev. 01





Report No.: FR020335A



Remote View

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: X7H-F800 Page Number : B4 of B4
Report Issued Date : Apr. 21, 2010
Report Version : Rev. 01